

halcyan
water conditioners

Bathhouse and Spa, Heat Exchanger Report

13 December 2012


Subject: Halcyan Model H2o 34 Testimonial

We have had major issues with mineral water fouling up heat exchangers.



After 7 Days Maintenance Had To Be Carried Out

The exchanger maintenance was outsourced and disassembled and pressure cleaned on a weekly basis at a cost of \$300 per visit.



14 days After The Install

Since installing the Halcyan that maintenance has been extended to 6-8 weeks. The savings over 12 months are significant!! We will be looking at installing more next year. Thanks to Earl and the team at Halcyan.

Regards

John Webster , Facilities Services Manager, Hepburn Bathhouse & Spa

Best Destination Spa Experience-The Australian Travel & Tourism Awards 2010

Hepburn Bathhouse & Spa ACN 005 087 463 ABN 18 118 940 063 Telephone +6 13 5321 6000 Email info@hepburnbathhouse.com Mineral Springs Reserve Road Hepburn Springs Victoria 3461 Australia Facsimile +6 13 5348 4795 Web www.hepburnbathhouse.com

7 Zetland Road, Bristol, BS6 7AG

+44 (0)345 504 0656

info@halcyanwater.com

Halcyanwater.com

Company Number: 9711030